

# Exhibit CC



**From:** Karl Heinz Selmer [khse@owbunker.de]  
**Sent:** Friday, October 10, 2014 4:58 AM  
**To:** Gaus, Lukas  
**Subject:** SEAS PAN HAMBURG - TACOMA - 16.10.2014 - Sales Order Confirmation No. 119-28241  
**Attachments:** Sales Order Confirmation-119-Q0000025579.pdf

Dear Lukas,

thank you for your support.

Krgds  
Karl

**O.W. Bunker Germany GmbH**  
**WW Division**



Hapag-Lloyd AG  
 Ballindamm 25  
 D-20095 Hamburg  
 Germany

Neumühlen 11  
 D-22763 Hamburg  
 Germany  
 Phone: +49 40 3255900  
 Fax: +49 40 330471  
 Tax No. / Steuer Nr. 41/768/03458  
 E-mail: trading@owbunker.de  
 Internet: <http://www.owbunker.com>  
 Managing director: Götz Lehsten  
 HR B 100089  
 ING Bank N.V.  
 IBAN: NL26 INGB 0020 1180 31  
 IBAN: NL10 INGB 0651 3696 81  
 SWIFT: INGBNL2A

## Sales Order Confirmation

Sales Order No. 119-28241

We are hereby pleased to acknowledge receipt of your order as follows:

Vessel SEAS PAN HAMBURG (IMO: 9224300)

Hamburg 10. October 2014

Port TACOMA

Delivery date 16. October 2014

Seller O.W. Bunker Germany GmbH

Your ref.

Account MASTER AND/OR OWNER AND/OR CHARTERERS  
 AND/OR MV SEAS PAN HAMBURG  
 AND/OR HAPAG-LLOYD AG

Quantity	Unit	Product / Quality	Curr	Price	Unit	Supplier
2.900,00	MT	Fueloil 700 CST,3,5%	USD	523,00	MT	US OIL Delivery : Barge
1,00	LPS	Booming fee	USD	0,00	LPS	US OIL

Agent NORTON LILLY

Payment WITHIN 30 DAYS FROM DATE OF DELIVERY UPON PRESENTATION OF INVOICE  
 (ORIGINAL/TELEX/FAX). COPY OF DELIVERY RECEIPT WILL BE FORWARDED WHEN WE HAVE  
 RECEIVED SAME.

Remarks all per ISO8217 2005(E)  
 HALO GTC 2007 shall apply.

We thank you for this nomination.

Kind Regards

Karl Heinz Selmer

Direct +49 4032 5590 12  
 Mobile +49 151 276 276 80  
 Yahoo ID khse\_owbunker  
 E-Mail khse@owbunker.de  
 Office E-Mail trading@owbunker.de

**O.W. Bunker Germany GmbH  
WW Division**



**TERMS AND CONDITIONS.**

**SAMPLES:**

Measuring and sampling to be done at barge/tanktruck/shoreside manifold, and receiving Vessels crew is requested to witness and verify the measuring of quantity and the drawing and sealing of samples. These verified quantities as noted in the BDR as well as these samples taken are the only ones deemed representative, and any dispute regarding quality to be settled by testing these retained samples by an independent laboratory at port/place of delivery, and result of this testing is deemed to be final and binding for both parties.

**TERMS:**

The sale and delivery of the marine fuels described above are subject to the OW Bunker Group's Terms and Conditions of sale(s) for Marine Bunkers. The acceptance of the marine bunkers by the vessel named above shall be deemed to constitute acceptance of the said general terms applicable to you as 'Buyer' and to O.W. Bunker Germany GmbH as 'Seller'.

The fixed terms and conditions are well known to you and remain in your possession. If this is not the case, the terms can be found under the web address:

[http://owbunker.com/wp-content/uploads/2013/12/OWB\\_GTC\\_ValidFrom01092013.pdf](http://owbunker.com/wp-content/uploads/2013/12/OWB_GTC_ValidFrom01092013.pdf)

**GUIDELINES FOR RECEIVING BUNKERS:**

We strongly urge you to forward the information regarding: General Instructions and Guidelines for Bunkering, for Receiving Vessels, on page 3, soonest possible to your Chief Engineer onboard. Following the suggested Guidelines should minimize risk of quantity disputes. Please bear in mind that barge figures are the sole valid quantity determination, wherefore Chief Engineer's attendance onboard the barge is extremely important.

**OTHERWISE:**

Any errors or omissions in above Confirmation should be reported immediately.

**PLEASE INFORM US BY RETURN IF ABOVE NOMINATION DETAILS ARE NOT IN ACCORDANCE WITH YOUR UNDERSTANDING.**

**O.W. Bunker Germany GmbH**  
**WW Division**



**GENERAL INSTRUCTIONS AND GUIDELINES FOR BUNKERING, FOR RECEIVING VESSELS**

**BEFORE BUNKERING:**

Please make sure to check all information given by the supplier on Bunker Requisition Form or such similar form as the supplier presents via the barge. If you notice changes in quantity or quality please urgently contact the relevant person in charge in your own operations to have same verified.

Make sure to witness and verify initial measurements and ullaging onboard the barge before. ALL tanks to be checked and measured including actual temperature of cargo – also including those tanks said not to be included in the particular supply (idle tanks). Compare measurements and verify the quantities as per barge ullage tables. When in full agreement please sign the ullage/sounding report for Before Supply figures. If any disagreements with the measurements, temperature and thereby figures please advise this on the Sounding form or, if not allowed, on separate Letter of Protest (make sure to obtain signature and stamp from barge Master for receipt).

If surveyor attends please ensure the surveyor also participates in measuring all barge tanks before supply and verify the figures.

**DURING BUNKERING:**

Always place a watchman to witness safe operation including also proper and correct sampling. The watchman must ensure that sampling is done properly, as continuous drip sampling throughout the delivery, and that clean devices are used for sampling. Also the watchman must witness proper and correct division into minimum 4 (four) clean and new identical sample bottles, including proper labeling and sealing of ALL samples. Make sure original sample (cubitalner) is shaken vigorously for 3 minutes before splitting into the 4 sample bottles and that bottles are filled in several passes. All seal numbers to be inserted into the Bunker Delivery Receipt (BDR). The MARPOL sample must be one of these samples drawn under witnessing.

The watchman must pay special attention to the bunker hose, and any un-agreed attempts to transfer air via same should cause immediate stoppage unless the use of air is caused by stripping of barge tanks, which stripping to be agreed in advance by both parties. If air is blown on continued basis, and stoppage on the supply not possible for any reason, the incident to be stated on a Letter of Protest, which should also contain the time (hours from/to) that airblow was notified.

It is known in some areas that the so-called Cappuccino Effect may be used or attempted to be used during supply. Pay special attention hereto and take all necessary precautions to observe, which includes:

- During tank measurements before it should be notified whether there are signs of air on the measuring tape used for ullaging.
- Look carefully for any signs of bubbles or similar on the surface of the fuel when it is still onboard the barge.
- Agree with the barge when and if they are going to make stripping of their tanks.
- Check and note the draft fore, mid and aft on the barge before and after supply to compare.
- If any signs at all of cappuccino or similar (except eventual stripping, agreed in advance), please stop the supply immediately and compare supply quantities made so far.
- Contact vessel operator in charge and request notification to the Seller and Supplier immediately.
- If surveyor attending please ensure that the surveyor signs a Letter of Protest also.
- After stopping the bunker supply please wait minimum 1 hour to await bubbles to disappear and re-measure the barge jointly with barge Master.

**AFTER COMPLETION:**

Repeat the measurement, sounding and ullaging of the barge, including verification of temperature of each tank. Make sure also on completion to verify contents of ALL tanks, including those being idle.

Report (ullage) must be signed by all parties involved, including eventual nominated surveyor. If disagreements with the figures (mm, temperature) a Letter of Protest to be issued, but also such specific disagreements to be stated on the Ullage report covering "after" supply.

**QUANTITY COMPLAINTS:**

Receiving Vessel to inform discrepancies in writing latest upon completion of taking the bunkers.